
sterrett urban, llc 704 canter st raymore, mo 64083 patrick sterrett

6500 Troost PIEA

Neighborhood Planning and Development Committee

June 14, 2023



Area Context



Boundaries

Planning Area

- Location:
 - SWC of 65th Street, Troost Avenue
- Planning Area Size:
 - 1.19 acres
 - 1 parcel
 - 1 owner 6500 Troost, LLC Purchased August 2022



Existing Conditions

- Existing improvements constructed 1954 (AT&T)
- Two buildings
 - 6500 Troost
 - Three stories / 35,400 sf
 - 1015 E. 65th Street
 - Two stories / 15,000 sf
- Previous Use: Service Station
- Current tenants:
 - Spire (storage yard/parking lot)
 - Superior Woodcraft (portion of lower level, 6500 Troost)
 - Peter Kohl Restoration (lower level, 1015 E. 65th St)
- Vacancy approximately 75%



Plan Requirements

- Satisfy Country Club/Waldo Area Plan Guidelines
- Land Use: Mixed Use Community
- Design Guidelines
- Rezoning: B4-2 to UR
- Ten year timeframe for completion

Anticipated PIEA Assistance

• Tax Abatement (10 years 70%; 5 years 30%)

Plan Area located within Non-Distressed Census Tract

Potential Redevelopment Projects

Proposed Redevelopment

- Renovation of existing buildings and site
- Commercial space small office, restaurant, services
- \$4.5 \$5.0 million investment



Blight – Statutory Definition

- Insanitary or unsafe conditions
- Deterioration of site improvements
- Conditions which endanger life or property by fire or other causes

Predominance of one or more blighting factors above leads to:

- Retards provision of housing accommodations, OR
- Economic liability, OR
- Social liability, OR
- Menace to public health, safety, morals, or welfare

In present condition and use

INSANITARY OR UNSAFE CONDITIONS

- Environmental liabilities
 - Groundwater contamination, asbestos, mold
- Water intrusion
 - Roofs, south basement wall of 6500 Troost
- Obsolete/non-functioning building systems
 - Life safety, electrical, HVAC, plumbing
- Lack of accessibility
 - No operating passenger elevator
- Tripping hazards
 - Deteriorated pavement
- Trash/debris









DETERIORATION


- Aging and deteriorating improvements
 - Primary deterioration of roofs, windows
 - Failure of finishes
 - Secondary deterioration of pavement

















Blighting Factors – Summary

6500 Troost PIEA Planning Area				
Summary of Blighting Factors				
Planning Area	Parcels	Pct.	Area (sq. ft.)	Pct.
Total	1	100%	52,006	100%
Blighting Factors				
Insanitary or unsafe conditions	1	100.0%	52,006	100.0%
Deterioration of site improvements	1	100.0%	52,006	100.0%
Existence of conditions which endanger				
life or property by fire and other causes	1	100.0%	52,006	100.0%
Parcels with at least one blighting factor	1	100.0%	52,006	100.0%
Parcels with no blighting factors	0	0.0%	0	0.0%
Parcels with Predominance of Blighting Factors	1	100.0%	52,006	100.0%

Blighting Factors – Economic Liability

ECONOMIC LIABILITY

- Reduced, negligible income
- Low assessed values
 - \$2.50/lsf improvement vs. \$15.50-\$22.00/lsf
- Low tax revenue (\$8,355.13)
- Impaired economic value

Physical deterioration

Insanitary, unsafe conditions

High Vacancy (75%)

Blighting Factors – Social Liability / Menace...

SOCIAL LIABILITY

- Environmental liabilities
- Non-functioning, inadequate, nonexistent building systems
 Life safety, accessibility, utilities
- Noncompliance with modern codes

MENACE TO PUBLIC HEALTH, SAFETY, MORALS, WELFARE

- Deteriorated and insanitary conditions threat to health
- Unsafe conditions threat to safety

Qualifications Analysis - Conclusion

The 6500 Troost PIEA Planning Area of Kansas City, Missouri, as of September 13, 2022, in its present condition and use, is a "blighted area" according to the definition provided in Missouri's Industrial Development statutes (RSMo Ch. 100).

sterrett urban, llc 704 canter st raymore, mo 64083 patrick sterrett

6500 Troost PIEA

Neighborhood Planning and Development Committee

June 14, 2023